

TRUCK ID SHEET

CLAIM # 26 PC 00000022079

FILE # 08120018

UNIT : 2009 John Deere 620I Gator

VIN#: 1JUDUVX186MO30924

INTER. COND:

TYPE: UTV

SEAT MAKE: Manual

SPEC. EQUIPMENT: None

ENGINE: Kawasaki Twin Cylinder 4 cycle 23Hp

OIL LEVEL: Good

TRANSMISSION: CVT Hi/Low

LOCATION: Dutzow, MO

HOURS: 339 Hrs

PAINT COND.: Good

DOM: 2009

WHEELBASE: 79"

COOLANT LEVEL: Good

UNIT# 163706

Independent

FRAME: Steel

FUEL TANK: 5.3 Gal Plastic

SUSPENSION: 1,400

REAR SUSPENSION: Independent Strut

STEERING: Rack & Pinion

BRAKES: Hydro Assist

FRONT WHEELS: Aluminum

REAR WHEELS: Aluminum

TIRE	SIZE	/32	RECAP YES/NO	DAMAGE YES/NO	TIRE	SIZE	/32	RECAP YES/NO	DAMAGE YES/NO
------	------	-----	-----------------	------------------	------	------	-----	-----------------	------------------

LF	12"	23		x		x	RF	12"	23		x		x
LRFO	12"	25		x		x	RRFO	12"	25		x	x	

REMARKS: