

**TRAILER ID SHEET**

**CLAIM# 01843995**

**FILE# : 08070018**

**LOCATION: St. Louis, MO**

**TYPE: 2019 Great Dane**

**UNIT# 1112**

**VIN#: 1GRAP062XKB126615**

**DOM: 02/18**

**LENGTH: 53'**

**WIDTH: 102''**

**SIDES: 112''**

**INSULATION: None**

**PLATE# 09F8EZ MO**

**LINING: None**

**FLOOR: Wood**

**OUTER SKIN: Composite**

**REAR SUSPENSION: Air Ride**

**WHEELS: Steel**

TIRE	SIZE	/32	RECAP YES NO	DAMAGE YES NO	TIRE	SIZE	/32	RECAP YES NO	DAMAGE YES NO
------	------	-----	-----------------	------------------	------	------	-----	-----------------	------------------

LRRO	22.5	16		x	x		RRFO	22.5	17		x	x	
LRFI	22.5	16		x	x		RRFI	22.5	16		x	x	
LRRO	22.5	16		x	x		RRRO	22.5	15		x	x	
LRRI	22.5	16		x	x		RRRI	22.5	16		x	x	

**All tires burnt**