

Heavy Equipment Inspection Report

Company Athens Administrators			Company Loss Number AR201928		Today's Date	
B-Quip Equipment Rental			Equipment Owner B-Quip Equipment Rental			
Date of Loss 2-18-2020		Type of Loss		Location of Inspection – Actual Physical Location		
Year 2018		Make Vermeer		Model BC700XL	Type of Equipment Brush Chipper	Date of Manufacture 2018
Identification Number (PIN) 1VRC101VSJ1002018		Hours on Equip. 126		Engine MFG. Kohler ECH740		Engine Model / No. Cyls. EFI 25 HP /2 cyl
Engine Enclosures yes		Grill Guard		Vandalism Protect		Sweeps
						Forestry Package
Rubber Tire Equipment						
Front Tire Size L 185/80/13		%Worn 35%	Rear Tire Size L 185/80/13		%Worn 35%	4 Wheel Drive <input type="checkbox"/> Yes <input type="checkbox"/> No
R		R				
Fire Extinguisher/Type		Grapple Make		Grapple Size		Dual Arch <input type="checkbox"/> Yes <input type="checkbox"/> No
						Winch <input type="checkbox"/> Yes <input type="checkbox"/> No
Backhoe <input type="checkbox"/> Fixed <input type="checkbox"/> Extendable		Feller Buncher MFG.		Feller Buncher Size		Feller Buncher Model & S/N
Crawler Equipment						
Width of Track Shoe		No. Track Rollers		S.A.L.T. Tracks		EST% of U/C Worn
						Rear Ripper / Type
Winch / Type / Capacity			ROPS / EROPS Cab Screens <input type="checkbox"/> Yes <input type="checkbox"/> No			Dozer Blade Type / Style
Additional Equipment/Attachments/Accessories						
Guide Book Value – Quick Sale			Guide Book Value - Resale		Actual Cash Value / Market	
Remarks: Unit is a towable chipper 2" hitch						
Adjuster Ron Speraneo/ Ashley Hughes			Location Warrensburg, MO			Condition of Equipment Poor